Work Orde								:				Page 1
Item ID: Revision ID:	D4017-3			Accept				s s	etup	Start		
	Rib 8/4/2010 8/6/2010	Start Qty: 2.00 Req'd Qty: 2.00			Cust Item) Customer:	ID:				Stop		
Approvals:	Process Plan	1: MF	Date: <u>10 - 8 - 0</u>			ate:		R		Start Stop		
Sequence ID/ Work Center ID		Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reje Qty		Reject Number	Insp. Stamp
Draw Nbr	Revi	sion Nbr		-				-			· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·
D4017	В											
100 Large Fab		Memo		0.00				2				· :
Large Fab		1- Cut tub	e as per dwg D4017 and remove identify marks	S	An 1-08-04							
110		QC5- Inspect part com	pleteness to step on W/O		.02/04			(AD)				
QC Quality Control		Memo		0.00					-			4
120 Packaging Packaging		Identify as per dwg & S	Stock Location: WA	0.00 0.00 S/	40 -08·04			2				1

Dart Ae	rospace L	td							٤
W/O:			W	ORK ORDER CHANGE	S				
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto
Part No		PAR #:	Fault Cate	gory:	NCR: Yes	No DO	A:	Date: _	
	Res	olution:	Dispositio	n:	QA: N/C C	losed: _	Date:		
NCR:			WORK ORD	ER NON-CONFORMAI	NCE (NCI	R)			
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Section Action Description Chief Eng	Sign Date	& Sec	i cation ton C	Approval Chief Eng	Approva QC Inspecto

Work Order ID 60970

Tuesday, August 03, 2010 9:19:30 AM



Page 2

Item ID:

D4017-3

Accept

Tool # Plan

Code

Setup Start

Stop



Revision ID: Item Name:

Rib

Start Date:

Required Date: 8/6/2010

8/4/2010

Start Qty: 2.00

Req'd Qty: 2.00

Cust Item ID:

Customer:

Tool ID

Approvals:

Reference:

Process Plan: Date:

Tooling:

Date:

Run Start

Reject

Qty !

QC:

Date:

SPC (Y/N):

Date:

Sequence ID/

Work Center ID 130

Quality Control

Operation Description

QC21- Final Inspection - Work Order Release

Memo

Set Up/ **Run Hours**

0.00

0.00

Accept

Qty

Stop

Reject Number

Insp.

Stamp

W/O:	Ì		W	ORK ORDER CHANG	ES				
DATE	STEP	PRO	OCEDURE CHA	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto
Part No):	PAR #:	Fault Cate	egory:	NCR: Yes	No DC	 	Date:	
		lution:							
NCR:				DER NON-CONFORMA					
		Description of NC		Corrective Action Secti	ion B	Vorif	cation	Approval	Approva
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Dat	& Sec	on C	Chief Eng	QC Inspecto

Picklist Print

Tuesday, August 03, 2010 9:19:29 AM

Work Order ID: 60970

Parent Item: D4017-3

Parent Item Name: Rib



Start Date: 8/4/2010

Start Qty: 2.00

Required Date: 8/6/2010

Page 1

Required Qty: 2.00

Comments:


IPP RevA: new issue DD 09.11.26 verified by:EC per dwg RevA DD 10.03.06 verified by:EC IIDD 10.04.16 verified by:EC

IPP Rev:B as IPP Rev:C as per dwg RevB

Component Item ID/ Replacement Item ID/ Purch Item Location Location Seq ID Weasure Hand Oty per Kit Total Oty Date Issued Issued Status M304TS0.750W.049 Purchased No 100 f 442.4194 4.73 9.957895 304 SQ Tube .75x.75x.049W		D 10.04.10 VCIII	ied by:EC				1) 1				
M304TS0.750W.049 Purchased No 100 f 442.4194 4.73 9.957895			-					- •	Qty per	Kit		-		Status
304 SO Tube 75v 75v 040W				No		100	f			 3		Issued	Issued	
Location			essi au tis uluiu 1 0 11 (80 1								SAD		0-68.	- 04

			SAD	10=08-0
Location	Loc Qty	Loc Code		,
MAT	40.83646794			
113763	0			:
114323	20.0582189			49 - 84
114677	14.34201			
114835	6.436239	-		
MAT017	3.68448E-05			. *
114298	3.6845E-05			
WA	401.5829			
114992	101.5829		Gation	
115260	300		11.13 48	
		1		· ·

W/O:	rospace		WO	RK ORDER CHANGES			-		r
DATE	STEP	PRO	OCEDURE CHAI		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto
								· · · · · · · · · · · · · · · · · · ·	
Part No		PAR #: solution:							
NCR:		,	WORK ORDE	ER NON-CONFORMAN	CE (NCR	1)			
		Description of NC		Corrective Action Section E		Verific	ation	Approval	Approva
DATE	STEP	Description of NC Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Secti		Chief Eng	QC Inspect
	1 1		i l		ĺ		ł		
							٠		



Dart Ae	rospace	Ltd							<i>.</i>
V/O:			W	ORK ORDER CHANGES					
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	١,								
					ı				
Part No:		PAR #:	Fault Cate	egory: f	NCR: Yes N	lo DQA	<u>.</u>	Date: _	
	Re	esolution:	Disposition	on: (A: N/C Clo	sed:		Date: _	
NCR:		,	WORK ORD	ER NON-CONFORMAN	CE (NCR)				
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Section E Action Description Chief Eng	Sign & Date	Verifica Sectio		Approval Chief Eng	Approval QC inspector
			1 1		l l		Ī		1

NCR:		W	ORK OR	DER NON-CONFORMANC	E (NCR)			,	
		Description of NC		Corrective Action Section B		Verification	Approval	Approval QC Inspector	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng		
							•		
		,							